Docket No. 034942-000245 (formerly 110619CFB.US)

In the Drawings

The attached replacement and annotated sheet(s) of drawings include changes to FIG. 1

and FIG. 2 as follows:

FIG. 1 has been amended such that box 121 has been relabeled 139 for consistency with

the specification, and the descriptive legend has been changed from "chordic converter" to

"cordic converter" to thereby correct the misspelling.

FIG. 2 has been amended to re-route the connection 237 to the delay element 238, and to

insert cordic converter 139 of FIG. 1 in its proper place for consistency with FIG. 1 and the

remainder of the description.


Attachment: Replacement Sheet

Annotated Sheet Showing Changes




Robert E. Krebs, Thelen Reid & Priest, LLP Serial No.: 09/885,811 Filed: June 19, 2001


TRP Docket No.: 034942-245 Annotated Sheet Showing Changes





Robert E. Krebs, Thelen Reid & Priest, LLP Serial No.: 09/885,811 Filed: June 19, 2001 TRP Docket No.: 034942-245 Replacement Sheet







## ROBERT E. KREBS, THELEN REID & PRIEST LLP Serial No.: 09/885,811 Filed: June 19, 2001 TRP DOCKET NO.: 034942-245 Replacement Sheet

